BURNSIDE

ASSEMBLY INSTRUCTIONS

# 4-WAY FIXTURE :: 292/299 - 4WAY



PART LIST:

4X. UPRIGHT



4X. ARM



1X. CROSS-BOTTOM



1X. CROSS-TOP



8X. CONNECTOR



2X. 4IN STEM
CASTER (BRAKE)



2X. 4IN STEM
CASTER (NON-BRAKE)



8X. JOINT CONNECTOR BOLT
1/4"-20 X 1 5/8"



8X. HEX NUT
1/4"-20 TPI



1X. L - KEY
FOR 1/4-20

STEP 1:


JOINT CONNECTOR BOLT
1/4"-20 X 1 5/8"
CONNECTOR
HEX NUT
1/4"-20 TPI
CROSS-TOP
UPRIGHT

STEP 2:


ARM
CROSS-BOTTOM
HEX NUT
1/4"-20 TPI
CONNECTOR
JOINT CONNECTOR
BOLT 1/4"-20 X 1 5/8"
4IN STEM CASTER
(BRAKE)
4IN STEM CASTER
(NON-BRAKE)